
## **Replacement state of the Ring clutch**

## **PHILIPP**GROUP

## **CRITERIA FOR REPLACEMENT STATE OF THE RING CLUTCH**

Lifting devices are strictly recommended to be insprected by an expert annually considering the following criteria. Depending on the working conditions the inspections might be necessary in shorter intervals than only once a year. This might be caused by frequent use, increased wear, corrosion or heat treatment.

Prior inspection of the Ring clutch it must be cleaned. Within an inspection the following points have to be considered:



» Exceeding of upper or lower wear measurements

## TEST DIMENSIONS


	Load class	f <sub>min</sub> (mm)	d <sub>min</sub> (mm)	h <sub>max</sub> (mm)	
	2,5	13,0	12,0	16,0	
	5,0	19,0	15,5	22,0	
	10,0	25,0	22,5	27,0	
	26,0	38,5	31,0	37,0	






**Twisted coupling** 







If one of the above-mentioned points is fulfilled the Ring clutch has reached its replacement state and must not be used anymore.



PHILIPP GmbH · Lilienthalstr. 7-9 · 63741 Aschaffenburg · 🛇 + 49 6021 40 27-0 · 🞯 info@philipp-gruppe.de

VB3-UVV-007-en - 12/23 - PDF

www.philipp-gruppe.de

**TO BE REPLACED**